



**REPAIR
PRICER**

Richmond VA 23294

Sent: Fri, 09 Feb 2024 12:26

PREPARED BY:

Pricing Team

QUESTIONS?
CLICK HERE TO GET HELP



Summary

HVAC Contractor	\$30935	<div style="width: 45%;"></div>
Roofing Contractor	\$9540	<div style="width: 15%;"></div>
Mason	\$1757	<div style="width: 3%;"></div>
Window/Glass Contractor	\$538	
Concrete Contractor	\$478	
Gutter Contractor	\$425	

WHOLE PROPERTY REPORT:

\$43,433

The Whole Home Estimate Explained: You will notice that if you add up every item on your report, the total will never match the Whole Home Estimate total. Why? By using custom calculations we work out not only the individual cost to fix each item, but also the projected cost if ONE contractor per trade were to visit the property and fix all the items at one time. Don't worry, your report is not incorrect and the prices are not meant to match the totals.



#	Item	Pg	Action	Projected
MASON.				
1	Foundation walls mortar joints 18: most of the exterior window openings have missing mortar at the top corners, exposing the metal lentils. Have all open mortar joints at the window openings corrected by a licensed contractor.	10	Have all open mortar joints at the window openings corrected by a licensed contractor.	\$887
2	19: there is some minor damage to the masonry located at the side loading dock area. Also, there is a metal angle on the exterior top corner of the loading dock that is rusted and deteriorated.	10	Repair noted areas and seal as needed.	\$870
Sub-Total (Mason).				\$1,757
HVAC CONTRACTOR.				
3	75: the gas pack rooftop unit that services the front right office area has a manufacture date of 2006. This unit is in typical satisfactory condition. There are some damaged exterior cooling fins on the unit that should be corrected by a licensed hvac contractor.	20	Budget to replace two RTU units with newer models.	\$22,590
4	76: There is a second rooftop gas pack unit that services the left side of the office areas. This unit has a manufactured date of 2003. This unit is in typical satisfactory condition. This rooftop unit also has some damaged exterior cooling fins.	21	Price Included In Item 3. (Budget to replace two RTU units with newer models.)	
5	Cooling and air handler equipment 83: there is a air-conditioning unit located at the back portion of the rooftop. This unit has a manufactured date of 2007 and it is a 5 ton central air system. This unit appears to be in typical condition for being a rooftop unit. The line set insulation is deteriorated and missing.	24	Budget to replace with newer models.	\$8,345
Sub-Total (HVAC Contractor).				\$30,935
ROOFING CONTRACTOR.				
6	8: this is a flat roof system. Drain water should drain off of this roof within a 24 hour period of time. It appears as though there are random areas on this flat roof system that are retaining water and not draining properly. Also the coating is weathered and cracking, representing that this roof system needs to have a new coating applied to the surface.	6	Recoat roof to prevent moisture intrusion and extend life of materials .	\$9,540
Sub-Total (Roofing Contractor).				\$9,540
WINDOW/GLASS CONTRACTOR.				
7	17: Random areas of window glazing are cracked, weathered and aged. Some of the window glazing has been compromised. Have a qualified licensed contractor make all professional corrections to the exterior window glazing as needed.	9	Replace compound in noted areas.	\$538
Sub-Total (Window/Glass Contractor).				\$538
CONCRETE CONTRACTOR.				
8	21: The side entrance concrete steps has a small trip hazard at the bottom of the stairs. Have this corrected by licensed contractor for safety purposes.	11	Make repairs to steps to improve safety.	\$478

Prepared for: [REDACTED] | Prepared by: Pricing Team.



#	Item	Pg	Action	Projected
Sub-Total (Concrete Contractor).				\$478
GUTTER CONTRACTOR.				
9	ROOF DRAINAGE SYSTEMS 10: The gutters have debris in them, which will not let this gutter system drain properly. Recommend to have the gutter systems cleaned. This is for your information only.	7	Clean out gutters and downspouts, general service and repair.	\$425
Sub-Total (Gutter Contractor).				\$425

Thank you for choosing Repair Pricer

About Repair Pricer

Repair Pricer is the industry standard for converting inspection reports into accurate repair estimates during the complex home purchasing process, enabling all parties to act quickly and confidently during a critical period. Repair Pricer saves time and reduces stress for everyone when it matters most. To learn more about Repair Pricer, visit www.repairpricer.com



It is important you understand that the service provided by RepairPricer.com is purely for estimation and negotiation purposes. We do not guarantee that the prices we estimate for repairs on your report are the same that you will end up paying for that specific repair. Our pricing is based on the average cost for a similar repair in your area, and due to unknown factors or underlying issues that we are not privy to, actual repair cost may be substantially higher.